


1. Incident Name		2. Operational Period (Date/Time)		Assignment List ICS 204-OS	
3. Branch			4. Division/Group		
5. Operations Personnel		Name		Affiliation	
Operations Section Chief					
Branch Director					
Division/Group Supervisor					
6. Resources Assigned This Period "X" indicates 204a attachment with special instructions					
Resource Identifier	Leader	Contact Info #	# or Persons	Reporting info/Notes/Remarks	
7. Assignments:					
Safety Note: Commercial and recreational vessel traffic, reptiles in area					
8. Site # 2-E	9. Quad Name: Orangefield	10. NOAA Chart # 11343	11. TGLO Atlas Page # 2	12. County/Parish: Orange	
13. Site Information: Site 2-E consists of 6 inlets located on the East and West bank of Cow Bayou approximately 1 miles East of East Round Bunch Rd Bridge by Peggy's on the Bayou. This site is located just Southeast of Mule Island. The banks consist of brackish marsh flora and fauna.				14. Latitude: N 30°02'10"	
				15. Longitude: W 93°47'36."	
16. Closest Boat Ramp: Peggy's on the Bayou		17. Distance From Ramp: 1 Mile		18. Boat Type: Small, medium; aluminum or steel hull	
19. Directions From MSU Port Arthur: From MSU go north 0.4 miles on Hwy 69 service road to u-turn @ Hwy 365. Travel south on Hwy 69 for 3.1 miles to the clover leaf to Hwy 73 east & travel 4.7 miles & then merge onto Hwy 73/87. Travel 7.4 miles to East Roundbunch Rd./ 1442 & turn right & travel 2.5 miles to Bridge City Bait restaurant/marina on the right.				20. Closest Airport: Orange County Airport	
				21. Closest Helispot: Orange County Airport	
22. Trustee/Contact Numbers USCG 409-723-6500 TGLO 800-832-8224		23. Resources at Risk Atlas Priority: Medium Environmental: Salt/brackish marsh habitat, threatened osprey, alligator, wading birds Economic: Commercial and Residential area.		24. Width of Inlet: 60'	
				25. Water depth: 7'	
				26. Tidal Influence: Low	
				27. # of Personnel: 2-4	
28. Booming Strategy Recommendation: Boom should be configured in an exclusion and or deflection pattern as to prevent oil from entering cuts. Bring sufficient anchors and rope to accomplish task. The information contained in this plan is intended to be used as guidelines for spill responders. Actual circumstances will vary and will dictate procedures to follow. Reassess protective strategy performance daily and modify at least accordingly.					
				Economic contacts	
				Peggy's on the Bayou 409-886-1115 Burton Shipyard, Inc. 409-735-8250	
29. Prepared By:		30. Reviewed by (PSC):		31. Reviewed by (OSC):	
Assignment List		ICS 204 OS (Geographic Response Plan)		Updated: 10/14/13	

